

Midland Manufacturing Company

4800 Esco Drive
Fort Worth, TX 76140
817-478-4848 817-483-9815 FAX

MATERIAL SPECIFICATIONS

Gland	ASTM A536 Ductile (65-45-12) Epoxy Coated to 4 mil thickness
Grip Ring	CA 87850 Bronze (max of .09% lead)

MIDCO Series 3000 (Style 30) PERMA-GRIP RESTRAINING JOINT SYSTEM TECHNICAL DATA INFORMATION

Item: MIDCO C900 Restraining Joint

Method: Hydrostatic Pressure

Procedure: MIDCO restrainers were assembled on the ends of a C900 pipe. A MJ cap was assembled on the end with the MIDCO joints providing the restraint and sealing.

TEST 1: Sustained Pressure Test

- 1.1 Duration: 1000 hours
- 1.2 Test Pressure: 507 P.S.I.
- 1.3 No detectable failures
No damage to pipe

TEST 2: Cyclic Pressure

- 2.1 Range from 100 to 205 P.S.I
- 2.2 Cycle frequency 6 to 10 cycles / minute
- 2.3 Duration of 1,089,174 cycles
- 2.4 No failure of assembly nor damage to pipe

TEST 3: Improper Installation

This test was performed by deliberately installing the restraining joint improperly. This installation allowed the end of the pipe to "bottom out" into the fitting. Upon introduction of water pressure, the gland leaked at approximately 50 P.S.I. Continued tightening of the gland bolts allowed the assembly to sustain pressures above 200 P.S.I. without leaking. It is strongly recommended however, to follow the instructions and not to bottom out the pipe.